

BUILDER NOTE:

ALL STRUCTURAL MEMBERS ARE NOT THE RESPONSIBILITY OF ACSYS

C620	SKEWED CORNER CONNECTION DETAIL	ACSYS ®	REV DATE 12-11-07