



BUILDER NOTE:
 WHEN THIS CONDITION OCCURS, PLEASE COORDINATE WITH DOOR SUPPLIER TO VERIFY THAT THE GIRT WILL NOT INTERFERE WITH OVERHEAD DOOR OR DOOR FRAMING.

D650 OVERHEAD DOOR HEAD

ACSYS

REV DATE
 12-11-07